



Figure 1: Front of residence as viewed from edge of driveway along Vizcaino.



Figure 2: Story poles for detached garage. Tree in foreground proposed to be removed.



Figure 3: Story Poles for proposed master bedroom addition.



Figure 4: Non-conforming carport wall. The subject wall does not meet the composite setback requirements. The wall shall remain intact for the duration of construction, and any removal shall require the wall to be brought into a compliant location. The yellow/green string in the photo indicates the location of the 3' setback.



Figure 5: Interior of carport wall described in Figure 4.



Figure 6: Addition to enclose existing porch into conditioned space.



Figure 7: Story poles showing the addition as seen from the interior court yard.