Perry Newberry 2 SW of 4th – photos taken 2/7/2020



Figure 1Debris in drip line of oak



Figure 2 Debris in drip line of oak



Figure 4 Removed root



Figure 6 Removed root



Figure 7 Removed root



Figure 3 Removed root



Figure 5 Pile of removed roots



Figure 8 Construction material and debris in drip lines



Figure 9 Root sticking out of waste toter