

Exhibit C.

Note blue metal shingles covering holes left by missing wood shingles



RECEIVED

JUN 09 2017


City of Carmel-by-the-Sea
Planning & Building Dept.



RECEIVED

JUN 09 2017

City of Carmel-by-the-Sea
Planning & Building Dept.



RECEIVED

JUN 09 2017

City of Carmel-by-the-Sea
Planning & Building Dept.

Exhibit C.



Comparison intact
foundation

RECEIVED

JUN 09 2017

City of Carmel-by-the-Sea
Planning & Building Dept.

Exhibit C



deteriorating sw
foundation

RECEIVED

JUN 09 2017

City of Carmel-by-the-Sea
Planning & Building Dept.

Exhibit C

crawlspace view of
deteriorating
foundation
admitting daylight



RECEIVED

JUN 09 2017

City of Carmel-by-the-Sea
Planning & Building Dept.