

Northwest Corner of Junipero Street and Thirteenth Avenue




Figure 1 View of removed trees - stumps under hand ex



Figure 2 Trunk and root debris



Figure 3 Stump excavation



Figure 4 Trunk measurement



Figure 5 Trunk measurement



Figure 6 Trunk measurement